General Environmental Incident Summary

Incident: 4002 Date/Time Notice: 1/20/2016 1530 DEM Incident No:

Responsible Party: Farmers Union Oil Co DBA/ Pinnacle ST

Date Incident:1/20/2016Time Incident:1430Duration:County:MountrailTwp:156Rng:91Sec:28Qtr:SW

Lat: 48.30012 Long: -102.38550 Method: Interpolation from map

Location Description: 8744 Hwy 2 South

Stanley, ND 58784

Submitted By: Lynette Clawson Affiliation: Safety Director

Address: PO Box 459

City: Stanley State: ND Zip: 58784

Received By:

Contact Person: Lynette Clawson

PO Box 459

Stanley, ND 58784

Distance Nearest Occupied Building: Release Contained: Yes

Type of Incident: bulk farm scully system didn't work

Description of Released Contaminant: #1 dyed diesel fuel

Volume Spilled: Ag Related: No

EPA Extremely Hazardous Substance: Unknown Reported to NRC: Unknown

Cause of Incident:

filling fuel truck scully system didn't shut off causing truck to over fill / noticed pushed the emergency shutoff valve

Risk Evaluation:

none

of Fatalities: 0 # of Injuries: 0 Affected Medium: 09 - other

Potential Environmental Impacts:

none

Action Taken or Planned:

under the truck there is a second containment area in which has a huge grate area where all product went into underground tank that is designed for this type of situation. I immediately called a vac truck to come and remove the product from the tank under the ground and they disposed of it (grate was removed to make sure all product was out and tank completely empty.

Wastes Disposal Location: The vac truck took to disposal in Ross ND

Agencies Involved: NDDES, Local Emergency Manager, EPA

Updates

Date: 1/20/2016 Status: Reviewed - Follow-up Required Author: O'Gorman, Brian

Updated Volume:

Notes:

Spoke with the company representative at 16:30 regarding the release. According to the representative, the release was completely contained within a cement containment with 2,000- gallon collection tanks. These were vacuumed out, and the fuel was transported to an oil company in Ross for re-use as a fracking fluid. On-site followup needed to verify release stayed in containment area.

Date: 2/12/2016 Status: Inspection Author: Kannenberg, Derek

Updated Volume:

Notes:

Date: 02/11/2016. Time: 1445. Observers: Kathleen Kangas, Derek Kannenberg. Weather: sunny, 18 degress F, wind 9 mph NNE. Reported dyed #1 diesel spill from equipment failure. Emergency shutoff was activated once overflow was noticed. Spill apparently flowed into containment drain into holding tank, which was then vacuumed out. Light snow cover made verification difficult, but layout of site appears to encourage proper spill protection. No evidence of uncontained spill on site.